

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

BOWER BUILDING

HABS CA-2786

409-413 East Weber Avenue

Stockton

San Joaquin County

California

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David Greenwood, photographer, March 2004

CA-2786-1	South façade, looking north.
CA-2786-2	South façade, looking north with a 10-foot scale at lower left.
CA-2786-3	Detail of second story brick façade at 409-413 East Weber Avenue, looking north.
CA-2786-4	First floor interior of the shoe store at 43 East Weber Avenue, looking north.
CA-2786-5	First floor interior of the shoe repair equipment at 413 East Weber Avenue, looking south.
CA-2786-6	Interior of the second floor dance hall above 409 and 411 East Weber Avenue, looking north.
CA-2786-7	Interior of the second floor dance hall, looking north with a 10-foot scale to the left.
CA-2786-8	Interior column detail of the second floor dance hall, looking north.
CA-2786-9	Interior column detail of the second floor dance hall, looking north with a 10-foot scale toward center.
CA-2786-10	Interior of the second floor dance hall, looking south.
CA-2786-11	Interior of the second floor dance hall with a 10-foot scale at the right, looking south.

BOWER BUILDING
HABS CA-2786
INDEX TO PHOTOGRAPHS

CA-2786-12	Interior of the second floor dance hall showing tall and narrow window openings that have been boarded up, looking south.
CA-2786-13	Interior of the second floor dance hall showing tall and narrow window openings with 10-foot scale near center, looking south.
CA-2786-14	Interior detail of door surrounds with entablatures of winged sun disk, looking east.
CA-2786-15	Interior detail showing the frieze that is painted around the perimeter of the dance hall, looking southeast.